



Vdd = 5 Volts
Vss = Tierra o Negativo

```
Ir VAR bit  
  
Inicio:  
FREQOUT 7 , 1 , 38500  
Ir = in8  
DEBUG HOME, "Ir = ", BIN1 Ir ,CR  
PAUSE 20  
GOTO Inicio
```